

JONY


SEA CONSIENTE DEL CUIDADO DE SU VEHICULO

CARR. LAS PALMAS # 1571

MEXICO, PUERTO VALLARTA JAL. 48280 3221341545

Fig. 2: Identifying Instrument Cluster Connector Terminals
Courtesy of CHRYSLER CORP.

1993 Plymouth Grand Voyager



VIEW FROM WIRE END

- | | |
|----------------------|----------------------------|
| 1. Not Used | 8. Low Oil Pressure Switch |
| 2. Battery (B+) | 9. BUS (-) |
| 3. Decode 1 | 10. BUS (+) |
| 4. Not Used | 11. Ignition Feed |
| 5. Decode 2 | 12. Not Used |
| 6. Illumination Feed | 13. Not Used |
| 7. Ground (B-) | 14. Illumination Ground |

93C76382