

JONY


SEA CONSIENTE DEL CUIDADO DE SU VEHICULO

CARR. LAS PALMAS # 1571

MEXICO, PUERTO VALLARTA JAL. 48280 3221341545

**Fig. 9: Identifying Primary Timing Chain Aligning Marks**  
**CHRYSLER CORP.**

2001 Dodge Intrepid



G98I03489